

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	6	hogout and weld\$4	USPAT	OR	OFF	2004/11/17 14:40
L2	25	linear\$4 near (friction\$4 and weld\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 14:42
L3	22	2 and (dimension\$4 or mass or wt or weight or amount or size)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 14:42

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	20	linear\$4 near (friction\$4 and weld\$4) and (machin\$4 or remov\$4 near (excess\$4 or extraneous or material))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:36
L2	11	1 and (mass or wt or weight or buy near fly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:37
L3	413	linear\$4 near (friction\$4 or weld\$4) and weld\$4 and (machin\$4 or remov\$4 near (excess\$4 or extraneous or material))	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:44
L4	201	3 and (mass or wt or weight or buy near fly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:37
L5	0	4 and (buy near fly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:37
L6	0	3 and (buy near fly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:38
L7	5	(buy near fly)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:39
L10	4	3 and (machin\$4 or remov\$4) near (mass or amount or wt or weight)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2004/11/17 12:44